Work Order ID 57210 March 30, 2010 8:54:21 AM								Page 1			
Revision ID:	D412-702-111B		Accept					Setup	Start Stop		
	Harness Assembly 30/03/2010 Start Qty: 2.00 30/03/2010 Req'd Qty: 2.00			Cust Item I Customer:	D:				жор		
Approvals:	Process Plan:QC:	Date: <u>(0-3-30</u> Date:	Tooling: SPC (Y/N):		ate:		I	Run	Start Stop		
Sequence ID/ Work Center ID Draw Nbr	Operation Description Revision Nbr		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp
100 Packaging Packaging	Pick Kit Memo		0.00					le	to)3/.	/ 3 u	<u> </u>
110 '			0.00				Ş			/-	

Small Fab Small Fab

Memo

0.00

Assemble as per ICA D412-702 P79

QC5- Inspect part completeness to step on W/O

120

Memo

Quality Control

Work Order ID 57210

March 30, 2010 8:54:21 AM

Required Date: 30/03/2010



Page 2

Item ID:

D412-702-111B

Accept

Setup Start

Stop



Revision ID:

Start Date:

Item Name:

Harness Assembly

30/03/2010

QC:

Start Oty: 2.00 Req'd Qty: 2.00

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date: _____

Tooling:

Date:

Run Start



Date:

SPC (Y/N):

Set Up/

Date:

Stop

Sequence ID/ Work Center ID

130

Packaging

Operation **Description**

Identify as per dwg & Stock Location



0.00

Run Hours

Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Packaging

Memo

Memo

0.00

10-3-30 5 3

140

QC Quality Control QC21- Final Inspection - Work Order Release

0.00

0.00

10/03/309 CZ 10/3/30

Picklist Print

March 30, 2010 8:54:28 AM

Work Order ID: 57210

Parent Item:

D412-702-111B

Parent Item Name:

Harness Assembly

Comments:

IPP rev A 07.05.11 new issue EC

IPP Rev:B Removed Decal D3569 07-07-06 JLM



Start Date: 30/03/2010

Start Qty: 2.00

Required Date: 30/03/2010

Required Qty: 2.00

Component Item ID/ Item Name AN960JD10L

Replacement Mfg/ Item ID

Purch Purchased Bin Primary Item Location No

Last Location

Route Seq ID 100

Unit of Measure Each

Qty on Hand

Remaining Qty To Pick 2,885.000 8.0000

Qty

Issued

Date Issued

Status

Washer

Warehouse	Lo	Loc Oty		
Location				
Main Warehouse				
ST348		2885		
101291		16		
105793		49		
110985		2820		
lo	100	Each	30.0000	2.000

D3570-1

Bracket

Manufactured

Manufactured

No

No

30

3

27

Each

2.0000 30.0000

m1/0985

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST245A

46350 55311

100

8.0000



Shoulder Harness

D3579-047

Warehouse	Loc Oty	Loc Code
Location		
Main Warehouse		
ST273	8	
55118	2	
55682	6	

Picklist Print

March 30, 2010 8:54:28 AM

Work Order ID: 57210

Parent Item:

D412-702-111B

Parent Item Name:

Harness Assembly

Comments:

IPP rev A 07.05.11 new issue EC

IPP Rev:B Removed Decal D3569 07-07-06 JLM



Start Date: 30/03/2010

Required Date: 30/03/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name

MS21042L3

Replacement Mfg/ Item ID Purch Purchased

Bin Primary Item Location No

Last Location Route Seq ID 100

Unit of Qty on Measure Hand Each

Remaining 2,045.000 8.0000

Qty Qty To Pick Issued

Date Issued

Status

Page 2

Nut

Warehouse Location	Loc Oty	Loc Code
Main Warehouse		
ST300	2045	
110844	35	
111274	27	
111668	58	
112314	285	
113523	17	
113537	623	
113644	1000	

MS24694-S50

Purchased

No

100 Each


194.0000 8.0000




(1/2 BO 2)

Screw

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST289	194		
108936	6		
111020	18		
113538	170		113538



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.